

WOODS Η SCHOOL CYPRESS **GH**



ORIGINALLY BUILT: 2006

SIZE: 499,765 sq. ft.

ADDITIONS: 2010

RENOVATIONS: n/a

ROPOSAL INCLUDES: 9 P B



SAFETY & SECURITY **ENHANCEMENTS**

- fencing around portable buildings
- impact-resistant glass on doors and high-traffic areas
- additional lockdown buttons
- harden main front desk
- additional card readers on exterior doors
- provide classroom phones
- upgrade classroom and exterior door hardware
- upgrade intrusion detection panels and door prop alarms
- upgrade existing metal detectors



- improve high-speed wireless and internet access
- flex space technology
- language lab
- lending devices for library
- replacement of current technology
- special education needs
- wireless displays in classroom
- administrative staff technology

www.cfisd.net/bond



FACILITIES RENOVATIONS & ADDITIONS

- provide storage in auditorium
- refinish floor in boys' locker room
- refinish floor in both gyms •
- refinish floor in weight room •
- regrade football practice field •
- replace lighting on baseball/softball fields
- replace press box on football field •
- replace lights in both gyms
- replace synthetic turf on football field
- renovate art rooms
- renovate fine arts instrument storage .
- art room addition .
- band director tower
- baseball and softball renovations (dugouts, • accessories, etc.)
- black box addition
- orchestra addition
- outdoor storage for athletics •
- synthetic turf at baseball and softball fields •
- two additional tennis courts

- asset protection
 - add dedicated HVAC to IDF rooms
 - add generator back-up power to IDF
 - paint all interior surfaces
 - provide additional egress lighting
 - provide new A/V system and controls
 - provide refrigerant monitoring system
 - reinsulate hydronic system piping
 - renovate/replace paving joint sealants
- replace A/C in portable buildings
- replace carpet/VCT
- replace ceiling
- replace classroom/lab casework
- replace CO monitoring system
- replace daycare fall protection surface
- replace exterior aluminum doors
- replace furniture
- replace HVAC controls
- replace lighting controls
- restripe pavement markings
- #CFISDbond

This information is available in Spanish, Chinese or Vietnamese upon request.